



BRIGHT COOP, INC.
803 West Seale Street
Nacogdoches, Texas 75964
Phone (936) 564-8378 • Fax (936) 564-3281
Toll Free (800) 562-0730
E-mail info@brightcoop.com



Service Bulletin

Grounding Wire for Throttle Pedal – BC3-6560 only

Please be aware that there may be an issue with the ground for the throttle pedal on your forklift. Bright Coop has been notified of several failures in the field, and upon investigation, we were notified by the pedal manufacturer that the ground should be connected directly to the battery.

We are advising our customers, with a serial number less than 89, to run a ground wire directly to the battery. Please cut into the loom in the location as shown below and then cut the black wire. Then, using a butt splice, connect the black wire on the throttle side to the negative terminal of the battery, or the bolt welded to the frame directly adjacent to the battery.



Cut into loom here to splice. This is the right side of the cab on the outside.

Please contact Bright Coop at the number above with any questions.

BE BRIGHT

BUY RIGHT

BUY BRIGHT'S

SERVING THE POULTRY INDUSTRY FOR MORE THAN 50 YEARS